



1. SUBSTRATE PREPARATION

Mechanically preparing the substrate to remove contamination, curing compounds, additives and opening the pores of the substrate assists in proper priming of the substrate. Rectify cracking and repair surfaces with the following:



ARDEX RA 56

Low-Viscosity Rigid Hybrid Polyurethane Crack & Spall Repair

ARDEX RA 88 PLUS

Multi-Purpose Non Sag Epoxy Repair Adhesive

CONCRETE CRACK LOCK

Carbon Fibre Crack Bridging Stitch which can used with ARDEX RA 88 PLUS

ARDEX A45

Rapid Hardening & Drying Repair Mortar for internal repairs and dormant cracks

Test the floor for moisture. If it meets the requirements floor moisture not present, prime the floor with any of the following:





ARDEX P51

Solvent Free Primer and Bonding Agent

ARDEX P9

Single Part Primer for Smooth and Dense Surfaces

2. INSTALL SMOOTHING/SELF LEVELLING



ARDEX FINE FINISH

Smoothing for thicknesses featheredge – 3 mm

ARDEX FEATHER FINISH

Rapid drying smoothing for thicknesses featheredge – 3 mm

ARDEX K120

Economical levelling for thicknesses 2.5 – 12 mm

ARDEX K220

Low odour levelling for thicknesses 2 – 20 mm

ARDEX K12 NEW

Super smooth levelling for thicknesses 1.5 – 35 mm

ARDEX K10 REACTIV8

Long open time levelling for thicknesses 1.5 – 15 mm

ARDEX K15

Fibre reinforced levelling for thicknesses feather – any depth

ARDEX K55

Rapid drying levelling for thicknesses 1 mm - any depth

ARDEX ARDITEX NA

Flexible levelling for thicknesses feather – 12 mm

3. ADHESIVE FIX VINYL



ARDEX AF 142

Fast grab vinyl adhesive

ARDEX AF 180 MS

Heavy duty adhesive for areas with direct sunlight

Refer to the most current product datasheet and/or technical bulletin at www.ardexaustralia.com for installation instructions.

ARDEX AUSTRALIA PTY LTD